


APPROVED HYDRANTS  
 MEULLER SUPER CENTURION  
 CLOW MEDALLION  
 KENNEDY GUARDIAN

NOTES:

1. FIRE HYDRANT INSTALLATIONS SHALL BE INSPECTED PRIOR TO BACKFILLING.
2. FIRE HYDRANTS SHALL BE POWDER COATED FROM THE MANUFACTURE, YELLOW IN THE RIGH OF WAY AND RED FOR PRIVATE PROPERTY.
3. 36" MINIMUM CLEARANCE ON ALL SIDES (MAY INCLUDE SIDEWALK), 20" MINIMUM ONLY ON CURB SIDE.



# STANDARD FIRE HYDRANT ASSEMBLY

DATE: December 2023